ANNUAL DRINKING WATER QUALITY REPORT FOR 2021

wells are 320 feet deep. drilled into the San-Koty aguifer. An aquifer is a geological formation that contains water. to continually improve the quality of your water. Our town uses ground water provided by three wells you with a safe and dependable supply of drinking water. We want you to understand the efforts we make We are pleased to present to you this year's Annual Water Quality Report. This report is designed to inform you about the water and services we deliver to you every day. Our constant goal is to provide The three wells are located within the village limits. These

mains. It then gets stirred up when water flow rates increase through the water mains. iron will still settle out in the water mains. flushing removes these sediments. We have greatly reduced the amount of iron that goes out into the water distribution system, but some Over time iron accumulates at the bottom of the water Periodic

customers to be informed about their water quality. Operator Brad Bode at the Goodfield Water Department, 203 W Fisk Street, phone 965-2710. We want our If you have any questions about this report, or concerning your water quality, please contact Water

presence of these small amounts of contaminants does not necessarily pose a health risk. expected to contain at least small amounts of some contaminants. It's important to remember that the Federal and State laws. This table shows the results of our monitoring for the period of January to December 31^{st,} 2021. All drinking water, including bottled drinking water, may be reasonably The Village of Goodfield routinely monitors for contaminants in your drinking water according to

the public or take any action with regard to the item. presentation to a maximum of five minutes. The Village Board shall have discretion to enter into further dialogue with the member of the topic to be raised. For agenda of non-agenda items, any member of the public may address the Village Board but must limit the Village Clerk by noon on the Friday preceding the Regular Meeting, including your name and any relevant information regarding at 7:00p.m. For an item to appear on the agenda of a Regular Board Meeting, you must present the item to be discussed to the The Village Board meetings are conducted at the Village Hall (114 S Eureka Street, Goodfield, IL) on the $3^{
m rd}$ Thursday of each month

Your Village Officers & Employees

President: Jim Edwards

Trustees: Terry Nohl, Matt Ginder, Todd Perry, Nate Sauder and Roger Mullins

Public Works Admin: Josh Nohl, Water Operator: Brad Bode, Sewer Operator: Mike Carr

Treasurer: Teresa DeGrave, Clerk: Sheri Martin

Streets: Terry Nohl, Laborer: Terry Holliger & Kyle Fultz

Village Phone: 309-965-2517

mail: goodfield@telstar-online.net

Annual Drinking Water Quality Report

GOODFIELD

IL2034450

Annual Water Quality Report for the period of January 1 to December 31, 2021

This report is intended to provide you with important information about your drinking water and the efforts made by the water system to provide safe drinking water.

The source of drinking water used by GOODFIELD is Ground Water

For more information regarding this report contact:

Name Brad Bode

309-965-2710

Phone

Este informe contiene información muy importante sobre el agua que usted bebe. Tradúzcalo ó hable con alguien que lo entienda bien.

Source of Drinking Water

The sources of drinking water (both tap water and bottled water) include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally-occurring minerals and, in some cases, radioactive material, and can pick up substances resulting from the presence of animals or from human activity.

Contaminants that may be present in source water include:

Microbial contaminants, such as viruses and bacteria, which may come from sewage treatment plants, septic systems, agricultural livestock operations, and wildlife.

Inorganic contaminants, such as salts and metals, which can be naturally-occurring or result from urban storm water runoff, industrial or domestic wastewater discharges, oil and gas production, mining, or farming.

 Pesticides and herbicides, which may come from a variety of sources such as agriculture, urban storm water runoff, and residential uses.

 Organic chemical contaminants, including synthetic and volatile organic chemicals, which are by-products of industrial processes and petroleum production, and can also come from gas stations, urban storm water runoff, and septic systems.

 Radioactive contaminants, which can be naturally-occurring or be the result of oil and gas production and mining activities.

Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the EPAs Safe Drinking Water Hotline at (800) 426-4791.

In order to ensure that tap water is safe to drink, EPA prescribes regulations which limit the amount of certain contaminants in water provided by public water systems. FDA regulations establish limits for contaminants in bottled water which must provide the same protection for public health.

Some people may be more vulnerable to contaminants in drinking water than the general population.

Immuno-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly and infants can be particularly at risk from infections. These people should seek advice about drinking water from their health care providers. EPA/CDC guidelines on appropriate means to lessen the risk of infection by Cryptosporidium and other microbial contaminants are available from the Safe Drinking water Hotline (800-426-4791).

If present, elevated levels of lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. We cannot control the variety of materials used in plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to 2 minutes before using water for drinking or cooking. If you are concerned about lead in your water, you may wish to have your water tested. Information on lead in drinking water, testing methods, and steps you can take to minimize Exposure is available from the Safe Drinking Water Hotline or at heep://www.epa.gov/safewater/lead.

Source Water Information

WELL 1 (31419)	GW	Active	Inside Water Treatment Plant
WELL 2 (31420)	МЭ	Active	2 blocks west of Water Treatment Plant
WELL 3 (01753)	МЭ	Active	S OF F Fisk St. E of Existing Water Treatment Plant

Source Water Assessment

http://www.epa.state.il.us/cgi-bin/wp/swap-fact-sheets.pl. or call our water operator at 309-965-2710. To view a summary version of the completed Source Water Assessments, including: Importance of Source Water; Susceptibility We want our valued customers to be informed about their water quality. If you would like to learn more, please feel welcome to attend any of our regularly scheduled meetings. The source water assessment for our supply has been completed by the Illinois EPA. If you would like a copy of this information, please stop by City Hall to Contamination Determination; and documentation/recommendation of Source Water Protection Efforts, you may access the Illinois EPA website at

water supply did not indicate a viral contamination threat. been mitigated such that the source water is adequately protected; monitoring data did not indicate a history of disease outbreak; and the sanitary survey of theen with sound integrity and proper site conditions; a hydrogeologic barrier exists that prevents pathogen movement; all potential routes and sanitary defects have determination is based upon the completed evaluation of the following criteria during the Vulnerability Waiver Process: risk to Goodfield's source water. Source of Water: GOODFIELDBased on information obtained in a Well Site Survey, published in 1990 by the Illinois EPA, there were 12 potential sources of groundwater contamination that may pose a hazard to Goodfield's wells. However, the Illinois EPA has determined that several of these potential sources may now be of reduced into the wells should be minimized, well hydraulics were not considered to be a significant factor in the vulnerability determination. EPA's proposed Ground Water Rule, the Illinois EPA has determined that the Goodfield community water supply is not vulnerable to viral contamination. Community Water Supply's source water is not susceptible to contamination. Glenn's Standard Service Station (tanks removed); Goodfield Laundromat (out of business); and GTE changed to VerizonThe Illinois EPA has determined that the Goodfield potential sources in the site data table, have changed their status: to the village's source water protection area. remediations, which may be of concern. were not evaluated for this groundwater supply. the wells; monitoring conducted at the entry point to the distribution system; and the available hydrogeologic data on the wells. In anticipation of the U.S. Furthermore, information provided by the LUST database indicated nine additional sites, some of which may have However, Based on information provided by Goodfield's water supply officials, the following facilities, also indicated these sites have not been field verified by the Groundwater Section staff and may or may not be located in proximity Because the community's wells are constructed in a confined aquifer and the movement of pathogens Vogel Oil Co. changed to Freedom Oil; Cropmate Soil Lab changed to Midwest Welding and Testing; This determination is based on a number of criteria including: monitoring conducted the community's wells are properly constructed Hence, well hydraulics

corrosion of lead and copper in the water distribution system. these once every nine years. Village of Goodfield Water Supply has been issued a Vulnerability Waiver for testing of SOC's (Synthetic Organic Chemicals). The Village of Goodfield Water Supply has also been issued a Special Exception Permit for the addition of poly/ortho blend phosphates to prevent The Illinois EPA issued this waiver based on review of past testing data and aquifer formations which protect the aquifer from Phosphates of this type are added to many food products and are considered safe We are however required to test for

Lead and Copper

Definitions:

Action Level Goal (ALG): The level of a contaminant in drinking water below which there is no known or expected risk to health. ALGs allow for a margin of safety. Action Level: The concentration of a contaminant which, if exceeded, triggers treatment or other requirements which a water system must follow.

Lead	Copper	Lead and Copper
09/14/2019	09/14/2019	Date Sampled
0	1.3	MCLG
15	.3	Action Level (AL)
1.5	0.54	90th Percentile
0	0	# Sites Over AL
qdđ	mad	Units
z	Z	Violation
Corrosion of household plumbing systems; Erosion of natural deposits.	Erosion of natural deposits; Leaching from wood preservatives; Corrosion of household plumbing systems.	Likely Source of Contamination

Water Quality Test Results

The following tables contain scientific terms and measures, some of which may require explanation.	Definitions:
	which may requ

Level 1 Assessment:	Avg:
A Level 1 assessment is a study of the water system to identify potential problems and determine (if possible) why total	Regulatory compliance with some MCLs are based on running annual average of monthly samples.

Level

	Maximum Contaminant Level or MCL:	
the best available treatment technology.	The highest level of a contaminant that is allowed in drinking water. MCLs are set as close to the MCLGs as feasible using	occasions.

	Maximum Contaminant Level Goal or MCLG:
a margin of safety.	Maximum Contaminant Level Goal or MCLG: The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs allow for

MRDL:	Maximum residual disinfectant level or
is necessary for control of microbial contaminants.	Maximum residual disinfectant level or The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant

Water Quality Test Results

: mdd :qdd mrem: na: Treatment Technique or TT: millirems per year (a measure of radiation absorbed by the body) A required process intended to reduce the level of a contaminant in drinking water. milligrams per liter or parts per million - or one ounce in 7,350 gallons of water. micrograms per liter or parts per billion - or one ounce in 7,350,000 gallons of water. not applicable.

Regulated Contaminants

Arsenic - While your 2021 drinking water meets EPA standards for arsenic, it does contain low levels of arsenic EPAs standard balances the current understanding of arsenics possible health effects against the costs of removing arsenic from drinking water EPA continues to research the health effects of low levels of arsenic, which is a mineral known to cause cancer in humans at high concentrations and is linked to other health effects such as skin damage and circulatory problems.	Inorganic Contaminants Collection Hi	Total Trihalomethanes 2021 (TTHM)	Haloacetic Acids 2021 (HAA5)	Chlorine 12/31/2021	Disinfectants and Collection H Disinfection Date By-Products
on :	Highest Level F Detected	ω	7	3.3	ighest Level Detected
4.9 - 7.5	Range of Levels Detected	2.53 - 3.22	2.89 - 3.74	2.8 - 3.8	Highest Level Range of Levels Detected Detected
0	MCTG	No goal for the total	No goal for the total	MRDLG = 4	STOW .
10	MCT	80	60	MRDL = 4	3 C C
ਰਕੋਰ	Units	qqq	qdđ	wdđ	Units
z	Violation	N	z	z	Violation
Erosion of natural deposits; Runoff from orchards; Runoff from glass and electronics production wastes.	Likely Source of Contamination	By-product of drinking water disinfection.	By-product of drinking water disinfection.	Water additive used to control microbes.	Likely Source of Contamination

Combined Radium 226/228	Radioactive Contaminants	Zinc	Sodium	Nitrate [measured as Nitrogen]	Manganese	Iron	Fluoride	Barium
2021	Collection Date	2021	2021	2021	2021	2021	2021	2021
1	Highest Level Detected	0.022	150	0.07	50	0.021	0.536	0.24
0.837 - 0.837	l Range of Levels Detected	0.022 - 0.022	150 - 150	0.07 - 0.07	50 - 50	0.021 - 0.021	0.536 - 0.536	0.24 - 0.24
0	MCTG	S.		10	150		4	2
v	MCL	5		10	150	1.0	4.0	N
pCi/L	Units	udd	udd	uđđ	qdđ	udd	ppm	mdđ
Z	Violation	z	Z	z	z	z	z	Z
Erosion of natural deposits.	1 Likely Source of Contamination	This contaminant is not currently regulated by the USEPA. However, the state regulates. Naturally occurring; discharge from metal	Erosion from naturally occuring deposits. Used in water softener regeneration.	Runoff from fertilizer use; Leaching from septic tanks, sewage; Erosion of natural deposits.	This contaminant is not currently regulated by the USEPA. However, the state regulates. Erosion of natural deposits.	This contaminant is not currently regulated by the USEPA. However, the state regulates. Erosion of natural deposits.	Erosion of natural deposits; Water additive which promotes strong teeth; Discharge from fertilizer and aluminum factories.	Discharge of drilling wastes; Discharge from metal refineries; Erosion of natural deposits.